

## Extract of property visit photos to owners



View of the common walkway and grounds on the West side of the group looking South



Rusting of steel bolts and some rot evident on this balcony.



View of window lintel - all show signs of extensive rusting.



View of rear security gate - access to car parks.